

Accident

Aircraft Type and Registration:	EMB-145EP, G-SAJK
No & Type of Engines:	2 Allison Ae 3007/A1/1 turbofan engines
Year of Manufacture:	1999 (Serial no: 145153)
Date & Time (UTC):	10 October 2024 at 1800 hrs
Location:	Aberdeen Airport
Type of Flight:	Commercial Air Transport (Passenger)
Persons on Board:	Crew - 3 Passengers - None
Injuries:	Crew - 1 (Serious) Passengers - N/A
Nature of Damage:	No damage reported
Commander's Licence:	Airline Transport Pilot's License
Commander's Age:	33 years
Commander's Flying Experience:	1,831 hours (of which 1,371 were on type) Last 90 days - 100 hours Last 28 days - 48 hours
Information Source:	Enquiries made by the AAIB

During the aircraft turn-around, a member of cabin crew was removing the bin liner from the metal galley bin when they were distracted by a flight dispatcher handing them a document. The metal bin dropped onto their foot causing a bone fracture. The cabin crew member did not depart on the subsequent flight and received medical attention. To prevent reoccurrence, the operator is going to advise its cabin crew to use the galley trolley bins, instead of the galley fixed bin.